

# SERVICEGRAM

Exclusive **Monroe®** Technology Solution

VOL. 4 NO. 2

## CHALLENGE

### Air Suspension Issues

**Application: 2013-2018 Ram 1500**

The owners of Ram 1500 pickups love their trucks' air suspension – in the summertime. Unfortunately, many of these truck owners have discovered that as temperatures drop, they may experience a ride height change and Malfunction Indicator Lamp (MIL) illumination. To view the Ram service bulletin, [click here](#).



Ram 1500 pictured is at normal ride height.

## SOLUTION

### Monroe® Suspension Conversion Kits

Monroe offers a comprehensive, reliable solution for these vehicle owners: Monroe Suspension Conversion Kits that enable customers to save time and money by converting worn original equipment air suspensions to mechanical suspensions.

The new Monroe conversion kit covers the front-right, front-left and rear of 2013-2018 Ram 1500 trucks equipped with factory air suspensions. The new kit provides all of the components needed to help restore proper vehicle ride height and handling, including front strut assemblies, rear shock absorbers, rear coil springs, spring isolators and jounce bumpers.

Monroe provides detailed, step-by-step instructions to help ensure an efficient, high-quality repair.



Part Number	Location on Vehicle	Box
90028C1	Front Right	Box 1 of 3*
90028C2	Front Left	Box 2 of 3*
90028C3	Rear	Box 3 of 3*

\* To ensure a complete repair, all parts must be installed as depicted in installation guide.



**Gurus On Call** 8:30 am – 5:30 pm (Eastern), Monday-Friday  
**USA & Canada:** 1-800-325-8886 | [✉ Gurus@Driv.com](mailto:Gurus@Driv.com)

**MONROE.COM**